

Warning Label


Retrofit Installation Diagram



Connecter Block with Inline Fuse (High melting point of 125°C which make it a safe fuse to use)




Live and Dead End must be clearly identified.






Warning Label

Retrofit Installation Diagram




Live and Dead End must be clearly identified.



Insulating Sheet (Plastic)





<u>Fuse Holder</u>

<u>Fuse</u>

